


### Owasco Lake Watershed Inspection Program



Completed situations

October's Progress

"Blank"

Situation still in progress, no change to report. Information reported under comments is the last known development on the situation.

CC HD = Cayuga County Health Department

CC SWCD = Cayuga County Soil and Water Conservation District

ACOE = Army Corps of Engineers

ECO = Environmental Conservation Officer

COE = Code Enforcement Officer

OLWIP = Owasco Lake Watershed Inspection Program

ID #	Town	Violation					Date Identified	Status			Comments
		OLWRR	CC HD - Sanitary Code	NYS DEC	ACOE	None		Initial Contacts	In Progress	Complete	
2009-001	Owasco	X	X				10/20/2009	X	X	X	New septic system was installed. Black line from unknown location on the property had low fecal coliform count, indicating that it is not discharging effluent. Waiting for total phosphorus results. Sampling was performed by CC HD.
2009-002	Scipio					X	8/29/2009	X	X		Construction of home to continue. Sediment and erosion control practices incorporated. Beginning to dig for septic system.
2009-003	Scipio					X	3/16/2009	X	X		Retaining wall has failed due to poor installation and not addressing upslope water concerns, which were brought up to property owner by CC SWCD and OLWIP. Property owner will not respond to OLWIP's request for how situation will be solved. OLWIP will monitor site during rain/snow events for water quality violation (NYS DEC law) and hand situation over to NYS DEC.
2009-004	Fleming					X	8/13/2009	X	X	X	Drainage concern, but not a water quality issue. Outreached to neighbor to work to solve the issue. No response.
2009-005	Fleming	X	X				9/21/2009	X	X	X	New septic system installed. Grass has begun to grow at the site.
2009-006	Moravia					X	6/2/2009	X	X		Construction of roadway has begun and installation of utilities.
2009-007	Locke					X	11/2/2009	X	X	X	Passed onto Town and CC Solid Waste for opportunities to restore the site.

2009-008	Fleming			X			11/25/2009	X	X	X	Construction of home was completed. Contractor worked with NYS DEC to get proper approval to have more than one acre open at the site.
2009-009	Moravia					X	10/15/2009	X	X	X	Construction of home complete and yard has been stabilized.
2009-010	Owasco					X	10/20/2009	X	X		Following Town of Owasco's building permit with regards to stormwater practices
2009-011	Owasco					X	8/29/2009	X	X	X	Construction has been completed. Lawn established. Silt fence has been removed.
2010-001	Scipio					X	8/17/2010	X	X		Original complaintee notified me that the septic system has been installed and leachlines were less than 20 feet from the top of the streambank. Spoke with the CC HD who did not consider the ravine to be a watercourse (because it was not a numbered stream), thus allowing the leachlines to be placed at least 15 feet from the top of the streambank.
2010-002	Skaneateles	X		X			8/4/2010	X	X		Group met again to discuss progress on fixing piping system to prevent situation in the future. NYS DEC will begin drafting order when plan for fixing system has been submitted by engineer (due 12/1/10). Engineer has been in contact with several hydraulic engineers who are trying to determine how the break had occurred. One theory is that the pipe was faulty, damage was done during installation, or it was not properly installed, causing damage and/or stress to the pipe. OLWIP and CC SWCD are working on evaluating streambanks for the main branch of Dutch Hollow Brook and determining what work could be done and the associated cost to complete the project. Other possible benefits projects include installation of buffers which meet standards along the tributary and working with the Town of Skaneateles on installing parking and increasing visibility at the Mable Reynolds Nature Preserve on Benson Road. It is uncertain which projects will be implemented and how much the fine will be at this time. This will greatly depend on the associated costs of the projects.
2010-003	Fleming					X	8/18/2010	X	X	X	Concerned about organic build-up of material along his seawall. He thought that it may have been caused by a sewer issue. No sewer issue; material had collected during storms.

2010-004	Venice	X	X				2/22/2010	X	X		Property unoccupied until the spring. Property owners have agreed to have an engineer hired regarding the privy and outdoor shower.
2010-005	Fleming					X	2010-005	X	X		Attended 239 Committee where environmental impacts and suggestions were given. One concern was about a pond that had been previously constructed without ACOE oversight and the outletting of the bioretention ponds into the pond, as well as other stormwater concerns. Working with ACOE by providing maps and background on the stream and pond. ACOE working to determine jurisdiction and how to handle.
2010-006	Owasco					X	6/18/2010	X	X	X	Project Complete - Landscaping and Lawn Project down to lakeshore. Erosion and sediment control practices were incorporated until lawn was stabilized.
2010-007	Owasco					X	8/18/2010	X	X		Seeding has begun to grow. No areas were re-seeded.
2010-008	Niles	X	X				7/9/2010	X	X		CC HD sent letter to property owner because engineered plans had not been submitted by the deadline. CC HD has required that the property not be rented or occupied until a new, approved system has been installed.
2010-009	Owasco				X		6/11/2010	X	X	X	Issue passed onto the ACOE. Violation has been resolved by ACOE.
2010-010	Fleming					X	7/14/2010	X	X	X	Camera was placed through sewer line to see if there were any more holes. Camera went through smoothly and no other holes were detected.
2010-011	Fleming					X	7/28/2010	X	X		Construction/remodel of lakefront home. Silt fencing is in place and properly installed.
2010-012	Venice					X	8/12/2010	X	X	X	Experiencing lakeshore erosion. Met with property owner at site and gave some ideas, permitting information, and CC SWCD contractor list. Property owner in the process of contacting contractors to get quotes, then will be applying for a permit.
2010-013	Owasco					X	8/23/2010	X	X		Concerned about streambank erosion on property along Dutch Hollow Brook.

2010-014	Scipio		X				6/24/2010	X	X		CC HD sent letter to property owner because engineered plans had not been submitted by the deadline. CC HD has required that the property not be rented or occupied until a new, approved system has been installed.
2010-015	Owasco					X		X	X		Development continues. Continue to monitor retention ponds and further construction activity.
2010-016	Owasco					X	9/29/2010	X	X	X	Complaint about stockpiles of manure in corn field. After investigation, found that the stockpiles are located in the Skaneateles Lake Watershed. Referred complaint to Skaneateles Lake Watershed Agricultural Program. Stockpiles were not located near a stream in either watershed and were more than 50 feet downhill of roadside ditch.
2010-017	Moravia					X	9/29/2010	X			Ditching noted and GPS'ed extent. Working to have hydroseeding approved and scheduled.
2010-018	Owasco						9/24/2010	X	X		NYS DEC ECO and CC SWCD are working on plan for farm.
2010-019	Owasco					X	10/13/2010	X	X		New home construction. Worked with COE to have silt fence installed properly and extended to better protect the drainage swale along the front of the property.
2010-020	Niles						9/24/2010	X	X		There is one goat fenced into the stream.
2010-021	Niles					X	10/14/2010	X	X		Homeowner concerned about eroding streambank on property. Looked at concern and will be offering suggestions for stabilization.
2010-022	Moravia					X	10/26/2010	X	X		Demolition and construction of lakefront home. Town has permitted work; working with the CC HD to be sure the department approves of the work. Working with the contractor to implement sediment and erosion control practices.

Other Notes:

\*Eco-Talk Article - NYS DEC burning regulations.

\* Information about Asian clam was released to the public.